



Our Work

Project/Client Name: Undisclosed Fortune 100 Enterprise Data Center –
Perimeter Security Risk Analysis

Location: Portland, Oregon

End Date: August 2015

Role: Analysis and Risk Identification

Scope of Work

Identified potential security risk at Operations Center of a Fortune 100 Enterprise Data Center and recommended solutions.

Project Detail

The SiTESPAN team identified and recommended appropriate measures to remediate a vehicle protection risk identified in a recent analysis at the client's operations center. The remediation recommendations included the design and build of an anti-vehicle perimeter barrier with a 50' set-back and K-4 rating surrounding the exterior of the building, as well as appropriate perimeter protection that reduces the likelihood of an undetected breach in the rear of the property and tree line areas. The team also identified a vehicle access strategy that will provide segregation between employee/visitor/delivery traffic, while allowing space for additional screening of delivery vehicles when appropriate. An access control point to the data center area within the facility was also recommended.

